ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	7	Byatarayanapura
Street ID	**Street Name**	**Significant Landmark**
W0113, W0111	3rd Crs, NA	Behind Sampath Kumar House in Jakkur layout
Segment No.	**Total Length (m)**	
7/C-W0113/S115052	210.02	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	80.09	77.596830	13.072360	77.596550	13.071835	W0113	DEAD END
2	129.93	77.596950	13.072785	77.596665	13.071647	RI-S50	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvement to Roads in 18th cross Behind Sampath Kumar House in Jakkur layout in ward no 07 Byatarayanapura Kodigehalli Sub-Division Yelahanka zone	600000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvement to Roads in 18th cross Behind Sampath Kumar House in Jakkur layout in ward no 07 Byatarayanapura Kodigehalli Sub-Division Yelahanka zone	007-15-000016
Work Order No.	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/266/2014-15	02/02/2015	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
02/02/2015	01/02/2016	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
B M MUNIRAJU		0.00
Phone No.	**E-Mail ID**	

9886778826

Zone:	YELAHANKA	**Ward No:**	7	**Ward Name:**	Byatarayanapura	**Street ID:**	W0113, W0111

Field Inspection Details

Number of Trees	Any Other Information	Name
0		BASAVARAJU

Date of Inspection	Remarks
26/11/2016	COMPLETED

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	27/11/2016	25/12/2016	COMPLETED
SE	VASU K M	27/11/2016	25/12/2016	COMPLETED
EE	SRINIVAS REDDY	27/11/2016	25/12/2016	COMPLETED
AEE	RAJINIKANTH MALLI	27/11/2016	25/12/2016	COMPLETED
AE	BASAVARAJU	27/11/2016	25/12/2016	COMPLETED
AE	BASAVARAJU	26/11/2016	25/12/2016	COMPLETED